



## AD831 EVALUATION BOARD REV B PARTS LIST

ITEM	QTY	PART NO	DESCRIPTION	REF DES	NOTES
1	4	P51.1FCT-ND	SM Res, 1206, 51.1 Ohm	R201, 202, 203, 205	1, 5
2	1	P110FCT-ND	SM Res, 1206, 110 Ohm	R204	1, 5
3	0	-----	Not Installed	R206	6
4	0	-----	Not Installed	L201, 202,,203, 204	6
5	2	PCC820CQCT-ND	SM Cap, 0805, 82 pF	C201, 202	1, 5
6	8	ECU-V1H104KBW	SM Cap, 1206, .1 UF	C203, 204, 205, 206, 207, 208, 209, 212	1, 5
7	2	P00.0EMG-ND	SM Res, 0.0 Ohm 1/8W	C210, 211 positions	1, 5
8	2	ECS-HICC106R	SM Cap, C-Case, 10 UF Tant TEH Series	C213, <b>214</b>	1, 5, 7
9	3	BNC 9059-WHT	BNC Conn, RT Angle Wht Body, Gold Contacts	J201, 202, 203	2
10	3	01-2540-1-02	Binding Post Metal	J204, 205, 206	1, 5
11	1	AD831	PLCC 20 pin Mixer, IC	U201	4
12	1	-----	AD831 EVAL PWB		4

### Notes

1. Digikey Corp. PO Box 677, Thief River Falls, MN 56701 (800) 344-4539
2. H.H. Smith (Bisco Industries)
3. Concord (Bisco Industries)
4. ADI
5. Panasonic (Digi-Key)
6. Customer Install Only
7. **SILK ERROR ON C214 REVERSED**



# AD831 EVALUATION BOARD REV B



